

ABRASION RESISTANCE TEST APPARATUS



Features

- Specification: Asper JASO.
- Operating Voltage : $230 \pm 10\%$ /50Hz.
- 2Pole ON/OFF Toggle Switch for Main ON.
- Catridge Fuse Holder with Glass Fuse for Control.
- Push Buttons Provided for Test ON, Test OFF & RESET.
- PLA Make Relay.
- Indicators for Main ON, Test ON & Fault .
- Digital AC Voltmeter (300VAC;LC: 1V,Accuracy :0.5%+2Digits)
- Digital Length Counter in mm .
- Digital RPM Indicator.
- Tape Roughness: 150Micron.
- Motorised Movement.
- Manual Arrangement to turn the sample.
- **Asper our Continous R&D the specification may change.**